PORSF 11.3.18.1 V8

Question 10(c) SUMMARY TABLE DOCUMENTED RELEASE HISTORY OF THE SITE

Kinder Morgan Liquid Terminals Linnton Facility Portland, Oregon

		Portland, Oregon				
Location	Reported Estimated	Reported	Product	Comment		
	Volume (Gallons)	Ву	e ge, ve passion is to	e du la librariera de la companio d		
Dock Area	5-20	Phillips Petroleum	Gasoline	Drained from hose after product transfer.		
Dock Area	Unspecified	Phillips Petroleum	Fuel Oil	Details not available.		
GATX Bulk Head	Seepage	GATX	Oil	Oil seepage to river; bypassed subsurface seepage control system.		
Dock Area	50-100	US Coast Guard	Diesel Fuel	Lost during product transfer.		
Dock Area	5-10	Tidewater Barge	Unleaded Gasoline	Drained from hose after product transfer; 4-5 gallons.		
Dock Area	10	Unspecified	Oil	Released during product transfer.		
Dock Area	0.5	GATX	Diesel Fuel	Pinhole leak in transfer line along shore. Sheen on river. Unspecified amount of soil removed. Greater than 213 gallons recovered from monitoring wells; actual volume unknown.		
Dock Area	Sheen	GATX	Diesel Fuel	Sheen on river.		
Dock Area	20	US Coast Guard	Unleaded Gasoline	Ten-inch valve cracked in two. Most gasoline contained in dock containment.		
Dock Area	200	GATX	Unleaded Gasoline	Check valve in 6-inch dock transfer line broke.		
Tank Farm	Unknown	Kinder Morgan	Unleaded Gasoline	Discovery of stain under a tank valve. The impacted gravel area was removed. Cleanup was deemed completed.		
Tank 55021	Unknown	Kinder Morgan	Product	Rivet was weeping product through the epoxy coating and was reported.		
Dock Area	Unknown	Kinder Morgan	Fire Fighting Foam	Release of fire fighting foam to the Willamette River from an oil/water separator due to the separator being overwhelmed due to the rain. Area was boomed off. Delta's March 12, 2008 Fire Fighting Foam Release Report is included as an attachment to Question 15.		
	Dock Area GATX Bulk Head Dock Area Dock Area Dock Area Dock Area Dock Area Tank Farm Tank 55021	Estimated Volume (Gallons) Dock Area 5-20 Dock Area Unspecified GATX Bulk Head Seepage Dock Area 50-100 Dock Area 10 Dock Area 10 Dock Area Sheen Dock Area 20 Dock Area 20 Tank Farm Unknown Tank 55021 Unknown	Location Reported Estimated Volume (Gallons) Dock Area 5-20 Phillips Petroleum Dock Area Unspecified Phillips Petroleum GATX Bulk Head Seepage GATX Dock Area 50-100 US Coast Guard Dock Area 10 Unspecified Dock Area 10 Unspecified Dock Area 20 GATX Dock Area Sheen GATX Dock Area 20 GATX Dock Area Sheen GATX Tank Farm Unknown Kinder Morgan Tank 55021 Unknown Kinder Morgan Kinder Morgan	Location Reported Estimated Volume (Gallons) Dock Area 5-20 Phillips Petroleum Fuel Oil Dock Area Unspecified Phillips Petroleum Fuel Oil GATX Bulk Head Seepage GATX Oil Dock Area 50-100 US Coast Guard Diesel Fuel Dock Area 10 Unspecified Oil Dock Area Sheen GATX Diesel Fuel Dock Area 20 US Coast Gasoline Dock Area Sheen GATX Unleaded Gasoline Dock Area 10 Unspecified Oil Tank Farm Unknown Kinder Morgan Unleaded Gasoline Tank Farm Unknown Kinder Morgan Product		

Notes:

- * release identified in October 2002 Draft Remedial Investigation prepared by KHM Environmental (provided as an attachment to Question 15).
- ** release identified in National Response Center Database; report attached.
- *** release identified in KMLT database search. Search results attached.

